

FORM
6
Rev
11/20

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE	ET	OE	ES
----	----	----	----

Replug By Other Operator

Document Number:
402815496
Date Received:
10/07/2021

WELL ABANDONMENT REPORT

This form is to be submitted as an Intent to Abandon whenever an abandonment is planned on a borehole. After the abandonment is complete, this form shall again be submitted as a Subsequent Report of the actual work completed. The approved intent shall be valid for six months after the approval date, after that period, a new intent will be required. Attachments required with the Intent to Abandon are wellbore diagrams of the current configuration and the proposed configuration with plugs set. A Subsequent Report of Abandonment shall indicate the actual work completed. Attachments required with a Subsequent Report are a wellbore diagram showing plugs that were set and casing remaining in the hole, the job summaries from all plugging contractors used, including wireline and cementing (third party verification) and any logs that may have been run during abandonment.

OGCC Operator Number: 10651 Contact Name: Brian Stanley
Name of Operator: VERDAD RESOURCES LLC Phone: (435) 6406426
Address: 1125 17TH STREET SUITE 550 Fax: _____
City: DENVER State: CO Zip: 80202 Email: bstanley@verdadresources.com

For "Intent" 24 hour notice required, Name: _____ Tel: _____
COGCC contact: Email: _____

Type of Well Abandonment Report: Notice of Intent to Abandon Subsequent Report of Abandonment

API Number 05-123-06133-00
Well Name: MCCLINTOCK ET AL Well Number: 1
Location: QtrQtr: NESE Section: 24 Township: 2N Range: 64W Meridian: 6
County: WELD Federal, Indian or State Lease Number: _____
Field Name: TAMPA Field Number: 80830

Only Complete the Following Background Information for Intent to Abandon

Latitude: 40.121955 Longitude: -104.492518
GPS Data: GPS Quality Value: 1.6 Type of GPS Quality Value: PDOP Date of Measurement: 06/29/2021
Reason for Abandonment: Dry Production Sub-economic Mechanical Problems
 Other _____
Casing to be pulled: Yes No Estimated Depth: _____
Fish in Hole: Yes No If yes, explain details below
Wellbore has Uncemented Casing leaks: Yes No If yes, explain details below
Details: _____

Current and Previously Abandoned Zones

Formation	Perf. Top	Perf. Btm	Abandoned Date	Method of Isolation	Plug Depth

Total: 0 zone(s)

Casing History

Casing Type	Size of Hole	Size of Casing	Grade	Wt/Ft	Csg/Liner Top	Setting Depth	Sacks Cmt	Cmt Btm	Cmt Top	Status
SURF	12+1/4	8+5/8	J55	32	0	166	150	166	0	VISU

Plugging Procedure for Intent and Subsequent Report

CIBP #1: Depth _____ with _____ sacks cmt on top. CIBP #2: Depth _____ with _____ sacks cmt on top.
CIBP #3: Depth _____ with _____ sacks cmt on top. CIBP #4: Depth _____ with _____ sacks cmt on top.
CIBP #5: Depth _____ with _____ sacks cmt on top.

NOTE: Two(2) sacks cement required on all CIBPs.

Set 50 sks cmt from 7306 ft. to 7162 ft. Plug Type: OPEN HOLE Plug Tagged:
Set 140 sks cmt from 6727 ft. to 6395 ft. Plug Type: OPEN HOLE Plug Tagged:
Set 60 sks cmt from 2507 ft. to 2386 ft. Plug Type: OPEN HOLE Plug Tagged:
Set 177 sks cmt from 900 ft. to 392 ft. Plug Type: OPEN HOLE Plug Tagged:
Set _____ sks cmt from _____ ft. to _____ ft. Plug Type: _____ Plug Tagged:
Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
Perforate and squeeze at _____ ft. with _____ sacks. Leave at least 100 ft. in casing _____ CICR Depth
(Cast Iron Cement Retainer Depth)
Set 146 sacks half in. half out surface casing from 220 ft. to 0 ft. Plug Tagged:
Set _____ sacks at surface
Cut four feet below ground level, weld on plate Above Ground Dry-Hole Marker: Yes No
Set _____ sacks in rat hole Set _____ sacks in mouse hole

Additional Plugging Information for Subsequent Report Only

Casing Recovered: _____ ft. of _____ inch casing Number of Days from Setting Surface Plug to Capping or Sealing the Well: 9
Surface Plug Setting Date: 09/08/2021 Cut and Cap Date: 09/17/2021
*Wireline Contractor: _____ *Cementing Contractor: Cementers Well Service
Type of Cement and Additives Used: 15.8 PPG Class G Neat
Flowline/Pipeline has been abandoned per Rule 1105 Yes No

Technical Detail/Comments:

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: _____ Print Name: Brian Stanley
Title: Completions Engineer Date: 10/7/2021 Email: bstanley@verdadresources.com

Based on the information provided herein, this Well Abandonment Report (Form 6) complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: Jacobson, Eric Date: 12/22/2021

CONDITIONS OF APPROVAL, IF ANY:

Condition of Approval

COA Type

Description

0 COA

Attachment List

<u>Att Doc Num</u>	<u>Name</u>
402815496	FORM 6 SUBSEQUENT SUBMITTED
402830821	CEMENT JOB SUMMARY
402830822	OPERATIONS SUMMARY
402830848	WELLBORE DIAGRAM
402830850	LOCATION PHOTO

Total Attach: 5 Files

General Comments

<u>User Group</u>	<u>Comment</u>	<u>Comment Date</u>
		Stamp Upon Approval

Total: 0 comment(s)