



99999999

DO OIL & GAS CONSERVATION COMMISSION
FIELD INSPECTION REPORT☒ NOTICE OF UNSATISFACTORY INSPECTION1120 Lincoln Street, Suite 801
Denver, CO 80203
(303)894-2100☐ NOTICE OF SATISFACTORY INSPECTION

API No. 05- <u>075 - 06413</u>	LEASE NAME: <u>mt. Hope 15</u>				
LOCATION: <u>NWSE-19-9N-53</u>	OPERATOR: <u>Monsieur / Shell?</u>				
DATE: <u>5-19-98</u>	INSPECTOR: <u>Ed Burt Day</u>				
Insp. Type: <u>SR</u>	Insp. Status: <u>PA</u>	PA: Y <input type="checkbox"/> N <input checked="" type="checkbox"/>	Pass/Fail: P <input type="checkbox"/> F <input checked="" type="checkbox"/>	Viol.: Y <input checked="" type="checkbox"/> N <input type="checkbox"/>	NOV: Y <input type="checkbox"/> N <input type="checkbox"/>

INSPECTION ITEM

COMMENTS

INPUT

Well ID Signs (Rule 210, 604.c(4))	<u>Risers, work pit, cellar open.</u>	
Pits (Reserve/Production) (Rule 902, 903, 904, 905)		
Fences (Rule 603.b.7, 604.C.(3), 1002.A)		
Tank Battery Equipment (Rule 603.b.3, 604)		
Fire Walls/Berms/Dikes (Rule 603.b.12, 604)		
General Housekeeping (Rule 603)		
Spills (Oil/Water) (Rule 907)		
Bradenhead (Rule 207.b)		
Drilling Well/Workover (Rule 317)		
Surface Rehabilitation (Rule 1002, 1003, 1004, 1103)		
Miscellaneous		

JUN 26 1998

CORRECTIVE ACTION REQUIRED: Remove risers, close cellar and
excavations and restore to grass.Date Corrective Action Required By: 6-15-98

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.



00270044