



99999999

DO OIL & GAS CONSERVATION COMMISSION
FIELD INSPECTION REPORT

<input checked="" type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION		1120 Lincoln Street, Suite 801	
<input type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION		Denver, CO 80203	
		(303)894-2100	
API No. 05- 075 - 6524		LEASE NAME: Henderson 5	
LOCATION: SWNW 18-9N-53		OPERATOR: Walsh	
DATE: 7-18-97		INSPECTOR: Ed Binkley (970) 8424465	
Insp. Type: SR	Insp. Status: PA	PA: Y <input checked="" type="radio"/> N <input type="radio"/>	Pass/Fail: P <input checked="" type="radio"/> F <input type="radio"/>
		Viol.: Y <input checked="" type="radio"/> N <input type="radio"/>	NOV: Y <input type="radio"/> N <input type="radio"/>

INSPECTION ITEM	COMMENTS	INPUT
Well ID Signs (Rule 210, 604.c(4))		
Pits (Reserve/Production) (Rule 902, 903, 904, 905)		
Fences (Rule 603.b.7, 604.C.(3), 1002.A)		
Tank Battery Equipment (Rule 603.b.3, 604)		
Fire Walls/Berms/Dikes (Rule 603.b.12, 604)		
General Housekeeping (Rule 603)		
Spills (Oil/Water) (Rule 907)		
Bradenhead (Rule 207.b)		
Drilling Well/Workover (Rule 317)		
Surface Rehabilitation (Rule 1002, 1003, 1004, 1103)		
Miscellaneous	Finish to p plug and restore site - - Check Form 10 -	

CORRECTIVE ACTION REQUIRED: Finish plugging and restore site.

Date Corrective Action Required By: 1-18-98 Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.