

Harrier 44-33





Installed appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1),(2).





Maintained vegetation per Rule 606.