

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/10/2022

Submitted Date:

01/10/2022

Document Number:

699503437**FIELD INSPECTION FORM**Loc ID 317738 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|---------------|----------------|----------------------------------|----------------------------------|
| , KPK | | cogcc@kpk.com | All Inspections |
| Watzman, Ross | (303) 825-4822 | rwatzman@kpk.com | all inspections. |
| , | | dnr_cogccengineering@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------------------|-------------|
| 239892 | WELL | PR | 12/14/2015 | GW | 123-07680 | FERN MILLER WIKSTRAND 2 | PR |

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

OTHER

Comment:

Missing wellhead bolts were observed during inspection with signs of mechanical issues at time of inspection. Mechanical integrity of well may need to be tested to ensure mechanical integrity of wellbore, and wellhead equipment. Contact COGCC engineering. See pictures 2

Corrective Action:

Comply with COGCC mechanical integrity testing rules.

Date: 01/10/2022

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Bradenhead

1

Comment:

Plumbed to surface

Corrective Action:

Date:

Type: Pump Jack

1

Comment:

Corrective Action:

Date:

Type: Prime Mover

1

Comment:

Gas motor

Corrective Action:

Date:

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 239892 Type: WELL API Number: 123-07680 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 10/29/2021 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: -- Fluid Type: End Surf Csg Pressure: --

Comment:

Corrective Action:

Date:

COGCC Comments

Comment

User

Date

COGCC Inspection Report Summary
 On 1/10/22 I, Inspector Justin Medina conducted an on-site inspection at:
 Well Name- Fern Miller Wikstrand 2
 Company Name- KPK
 API- 05-123-07680
 In Weld County Colorado.
 While there, I observed PR well
 During this inspection the following possible compliance issues were observed:
 Missing wellhead bolts were observed during inspection with signs of mechanical issues at
 time of inspection. Mechanical integrity of well may need to be tested to ensure mechanical
 integrity of wellbore, and wellhead equipment. Contact COGCC engineering. See picture
 2.
 Comply with COGCC mechanical integrity testing rules. 1/10/21
 A follow up on this site inspection needs to be conducted to ensure the compliance issues
 have been corrected to comply with COGCC rules.
 This is a summary of inspection report.

medinaj

01/10/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---------------------|---|
| 699503438 | Inspection pictures | http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5629690 |