

TEP
Mobile
Location # 322510



location



location

TEP
Mobile
Location # 322510



Location/lack of battery signage



Lack of labeling

TEP
Mobile
Location # 322510



Labeling falling off



Lack of bull plug/cap

