

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/24/2022

Submitted Date:

01/25/2022

Document Number:

693700917**FIELD INSPECTION FORM**Loc ID 422460 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10671Name of Operator: EDGE ENERGY II LLCAddress: 600 12TH STREET SUITE 115City: GOLDEN State: CO Zip: 80401**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Wheeler, Steven		steven.wheeler@state.co.us	
Ben Turner		bturner@edgeenergy1.com	
Whittington, Ellice		ellice.whittington@state.co.us	
MacLaren, Joe		joe.maclaren@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
422410	WELL	SI	06/01/2019	OW	069-06436	RAWHIDE FLATS 10-68-16 1H	EI

General Comment:

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Flow Line	# 1		
Comment:	Buried flowline from well to treater has been removed. No Form 42 pre-abandonment notice was submitted. A Form 42 Abandonment verification is also required.		
Corrective Action:	Submit a Form 42 - Abandonment of Flowlines within 90 days. Contact Engineering Integrity Engineer for guidance on submitting Form 43 Abandonment Notification after the fact.		Date: <u>04/24/2022</u>

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Environmental**Spill/Remediation:**

Comment: Operator has plugged and abandoned the well and is in process of abandoning the production equipment. Operator previously submitted a Form 27 Site Investigation Workplan which was returned to draft. Revised Form 27 has not been received.

No E&P Waste was observed stored onsite. Multiple pieces of equipment have been removed including: ASTs, Heater Treater, ECD, Gas Meter skid, and ancillary equipment.

Well has been cut & capped and excavation remains open.

Corrective Action: Form 27 must be resubmitted with a proposal indicating planned soil screening and soil sample locations, proposed soil sample analysis, and site map illustrating equipment locations and planned soil sample locations. Operator should refer to the to Rule 911.a.(4) - Oil and Gas Facility Closure Guidance Document and Rule 911.a.(4) checklists, as well as 915.e.(2) - Soil Sampling and Analysis Guidance Document. Operator shall include a schedule for sampling and followup reporting.

Date: 02/08/2022

At a minimum samples for laboratory analysis are required adjacent the well at base of excavation, beneath former flowline risers, beneath heater treater, beneath AST footprint (beneath the liner once removed). Minimum required soil analysis includes the following Table 915-1 Contaminants of Concern: TPH (C6-C36), benzene, toluene, ethylbenzene, total xylenes, 1,2,4-trimethylbenzene, 1,3,5-trimethylbenzene and soil suitability for reclamation parameters: electrical conductivity (EC), Sodium Adsorption Ratio (SAR), pH, and boron.

If impacts are observed Operator shall analyze soil samples for complete Table 915-1 Contaminants of Concern.

Corrective action date is date to resubmit Form 27 Workplan.

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
693700918	RawhideFlats10-68-16Photos1-24-2022	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5643271