

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402857657

Date Received:
10/29/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-3779

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Drew Stormo

970-336-3802

Drew.Stormo@Oxy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693903579

Inspection Date: 08/26/2021

FIR Submit Date: 08/30/2021

FIR Status: _____

Inspected Operator Information:

Company Name: WESTERN GAS RESOURCES INC

Company Number: 26400

Address: 1099 18TH ST

City: DENVER State: CO Zip: 80217

LOCATION - Location ID: 385549

Location Name: NORTH ALKALI GULCH-M34N12W Number: 22SWSW County: LA PLATA

Qtrqtr: SWS Sec: 22 Twp: 34N Range: 12W Meridian: M
W

Latitude: 37.171326 Longitude: -108.144107

FACILITY - API Number: 05-067- -00 Facility ID: 214574

Facility Name: NORTH ALKALI GULCH Number: 14-22

Qtrqtr: SWS Sec: 22 Twp: 34N Range: 12W Meridian: M
W

Latitude: 37.171326 Longitude: -108.144107

CORRECTIVE ACTIONS:

1 ☒ CA# 155299

Corrective Action: -Revegetation measures need to be installed where bare soils remain on the southwestern portion of the well pad cut-slope and in the southern project area where soils were disturbed for riser removal. Additional topsoil will likely be needed on the cut-slope as most soil has eroded down-slope.

-Weeds need to be managed and controlled.

Date: _____

Response: CA COMPLETED

Date of Completion: 10/19/2021

Operator Comment: Revegetation measures have been taken and topsoil added.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

2 ☒ CA# 155300

Corrective Action: Stormwater and erosion controls need to be installed on the cut-slope and in the southern project area where bare soils remain. Stormwater and erosion controls need to be installed and maintained until location is stabilized with desirable perennial vegetation.

Date: _____

Response: CA COMPLETED

Date of Completion: 10/19/2021

Operator Comment: Stormwater and erosion control measures have been installed.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Revegetation measures have been taken and topsoil added. Stormwater and erosion control measures have been installed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Callie Fiddes

Signed: _____

Title: Regulatory Analyst

Date: 10/29/2021 12:26:47 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402857657	FIR RESOLUTION SUBMITTED
-----------	--------------------------

Total Attach: 1 Files