

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402859063

Date Received:
11/01/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46685
Name of Operator: KINDER MORGAN CO2 CO LP
Address: 1001 LOUISIANA ST SUITE 1000
City: HOUSTON State: TX Zip: 77002
Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>.General</u>		<u>CO2Source_Regulatory@kindermorgan.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 693903732
Inspection Date: 10/11/2021 FIR Submit Date: 10/13/2021 FIR Status: _____

Inspected Operator Information:

Company Name: KINDER MORGAN CO2 CO LP Company Number: 46685
Address: 1001 LOUISIANA ST SUITE 1000
City: HOUSTON State: TX Zip: 77002

LOCATION - Location ID: 463480

Location Name: DC Number: 16 County: DOLORES
Qtrqtr: NWNE Sec: 18 Twp: 40N Range: 17W Meridian: N
Latitude: 37.733630 Longitude: -108.764990

FACILITY - API Number: 05-033-00 Facility ID: 463479

Facility Name: DC Number: 16
Qtrqtr: NWNE Sec: 18 Twp: 40N Range: 17W Meridian: N
Latitude: 37.733630 Longitude: -108.764990

CORRECTIVE ACTIONS:

1 ☒ CA# 156832

Corrective Action: -Stormwater and erosion controls need to be installed along the access road to reduce erosion and sediment discharge by 11/13/2021. Stormwater controls need to be selected, sized, installed, and maintained according to good engineering practices such as those described by CDOT in their erosion control manuals.

Date: 11/13/2021

Response: CA COMPLETED

Date of Completion: 10/29/2021

See attached photo log which shows 1) Slope along access road was broadcast seeded and covered with a certified weed free straw. 2) Soil amendments were applied to the slope and then the slope was seeded with a landowner approved seed mix. The slope was then covered with hydromulch in order to stabilize it.

Operator
Comment:

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jenna Emerick

Signed: _____

Title: EHS Specialist

Date: 11/1/2021 2:06:04 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number **Description**

402859063	FIR RESOLUTION SUBMITTED
402859092	Photo Log

Total Attach: 2 Files