

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402866530

Date Received:

11/09/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 2 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10749

Name of Operator: SIMCOE LLC

Address: 1199 MAIN AVE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

.General

sjninspections@ikavenergy.com

.General

sjninspections@ikavenergy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 693903724

Inspection Date: 10/06/2021

FIR Submit Date: 10/08/2021

FIR Status: _____

Inspected Operator Information:

Company Name: SIMCOE LLC

Company Number: 10749

Address: THREE ALLEN CENTER, 333 CLAY ST SUITE 3900

City: HOUSTON State: TX Zip: 77002

LOCATION - Location ID: 326119

Location Name: SOUTHERN UTE 32-10-N32N10W Number: 4SENE County: LA PLATA

Qtrqr: SENE Sec: 4 Twp: 32N Range: 10W Meridian: N

Latitude: 37.050386 Longitude: -107.932500

FACILITY - API Number: 05-067-00 Facility ID: 215904

Facility Name: SOUTHERN UTE 32-10; Number: 4-3

Qtrqr: SENE Sec: 4 Twp: 32N Range: 10W Meridian: N

Latitude: 37.050386 Longitude: -107.932500

CORRECTIVE ACTIONS:

2 ☒ CA# 156578

Corrective Action: -Stormwater controls need to be installed to stabilize erosion coming from the southern portion of the project area, and along the access road. Stormwater controls need to be selected, sized, installed, and maintained according to good engineering practices such as those described by CDOT in their erosion control manuals. Corrective action date: 11/8/2021.

Date: 11/08/2021

Response: CA COMPLETED

Date of Completion: 11/08/2021

Operator Comment:	Filled in erosion channels on east side of compressor, and installed wattles in run off channel on south side of location, as well as along ditch bank on access road. photos attached
COGCC Decision:	<u>Approved pending re-inspection</u>
COGCC Representative:	

OPERATOR COMMENT AND SUBMITTAL	
Comment:	1 CA completed
I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.	
Print Name: Karin Rhodes	Signed:
Title: admin asst	Date: 11/9/2021 3:33:38 PM

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Total Attach: 2 Files