

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402937807

Date Received:  
01/26/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 2 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

|                      |                     |                                              |
|----------------------|---------------------|----------------------------------------------|
| Contact Name         | Phone               | Email                                        |
| <u>Romana Cowden</u> | <u>720-951-5895</u> | <u>cogcc.inspections@caerusoilandgas.com</u> |

COGCC INSPECTION SUMMARY:

FIR Document Number: 696202051

Inspection Date: 11/24/2020

FIR Submit Date: 12/28/2020

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC

Company Number: 10456

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 312672

Location Name: Nichols Number: 31-11 County: \_\_\_\_\_  
(PL31SW)

Qtrqtr: NESW Sec: 31 Twp: 9S Range: 95W Meridian: 6

Latitude: 39.230150 Longitude: -108.037730

FACILITY - API Number: 05-077-00 Facility ID: 312672

Facility Name: Nichols Number: 31-11  
(PL31SW)

Qtrqtr: NESW Sec: 31 Twp: 9S Range: 95W Meridian: 6

Latitude: 39.230150 Longitude: -108.037730

CORRECTIVE ACTIONS:

1  CA# 145329

Corrective Action: Comply with Rule 1004.a and conduct additional reclamation on areas of the Location damaged due to vehicle travel on the Reclamation area.

Date: 05/01/2021

Response: CA COMPLETED Date of Completion: 03/04/2021

Operator Comment: Reclaimed and seeded ruts caused by traffic in reclaim area.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Approved pending re-inspection of this FIR resolution acknowledges the document was received. It is not an acknowledgement that the corrective action has been passed. Operator has provided no documentation attached to this resolution to show work has been conducted per corrective action(s). A field inspection will be conducted at a future date to evaluate compliance with COGCC rules.

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Romana Cowden

Signed: \_\_\_\_\_

Title: EHS

Date: 1/26/2022 12:58:02 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

|           |                          |
|-----------|--------------------------|
| 402937807 | FIR RESOLUTION SUBMITTED |
|-----------|--------------------------|

Total Attach: 1 Files