

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402943276

Date Received:

02/01/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10112

Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC

Address: 5057 KELLER SPRINGS RD STE 650

City: ADDISON State: TX Zip: 75001

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Beard, Alyssa</u>		<u>ABeard@foundationenergy.com</u>
<u>Foundation Energy</u>	<u>(866) 767-3600</u>	<u>regulatory@foundationenergy.com</u>
<u>Shalberg, Greg</u>	<u>(719) 688-3547</u>	<u>gregshalberg@aol.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 688311819

Inspection Date: 12/29/2021

FIR Submit Date: 12/30/2021

FIR Status: _____

Inspected Operator Information:

Company Name: FOUNDATION ENERGY MANAGEMENT LLC

Company Number: 10112

Address: 5057 KELLER SPRINGS RD STE 650

City: ADDISON State: TX Zip: 75001

LOCATION - Location ID: 387162

Location Name: STEGAS 34-15 Number: 2 County: LINCOLN

Qtrqtr: SWSE Sec: 15 Twp: 11S Range: 53W Meridian: 6

Latitude: 39.083590 Longitude: -103.318630

FACILITY - API Number: 05-073- -00 Facility ID: 218293

Facility Name: STEGAS 34-15 Number: 2

Qtrqtr: SWSE Sec: 15 Twp: 11S Range: 53W Meridian: 6

Latitude: 39.083590 Longitude: -103.318630

CORRECTIVE ACTIONS:

1 ☒ CA# 158989

Corrective Action: Inspect, maintain and repair tanks to comply with rule 609.b.

Date: 02/01/2022

Response: CA COMPLETED

Date of Completion: 01/31/2022

Operator Comment: The faulty tank at the Stegas location was removed.

COGCC Decision: Approved pending re-inspection

COGCC Representative: Very professional to remove tank and cleanup soils. Thank you.

2 ☒ CA# 158990

Corrective Action: Non E&P Waste not properly stored, handled, transported, treated, or disposed per Rule 906. Require appropriate cleanup.

Date: 02/01/2022

Response: CA COMPLETED

Date of Completion: 01/31/2022

Operator Comment: The salt-stained soil near and beneath the faulty tank was removed and taken for disposal at Pawnee Waste.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Alyssa Beard

Signed: _____

Title: EHSR Manager

Date: 2/1/2022 8:07:37 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402943276	FIR RESOLUTION SUBMITTED
402943277	Photo Documentation 1/31/22

Total Attach: 2 Files