

MacSoft VT #1

\*\*\* COGINS \*\*\*

WELL MASTER MAINTENANCE - INQUIRY MODE

CO1WM



00202341

API NUMBER	WELL CAT	COUNTY	BASIN	USER	MODDT
05 107 06178 0	D F	ROUTT	AXIAL	BJ1	B3192
OPERATOR/NAME		M'OWN DRILLER/CONT NAME			
66580 PACIFIC ENTERPRISES OIL CO		F	1 NAME/UNKNOWN		
PL S/PTY	SUR S/PTY	OBCC#	LEASE/NAME	WELL NUMBER	
G	A		PROC-NVG	32-26	
FIELD/NAME		FORM/NAME		#ACRES	DRLG UT
14250 CURTIS		NBRR NIOBRARA		160	
SPA/ORD	PERMIT#	APPROV	EXPIRE	SPUDDT	FM5 FT/(NS) FT/(EW)
	920541	52792	92492	N	1836 N 1934 E
QTR	SEC	TOWN	RANGE	N/S PM	LATITUDE
NWNE	26	6.0 N	86.0 W	6	-
1ST OIL	1ST GAS	FORM10	OIL GRAV	GAS GRAV	BTU O/C GAS FAC#

WLSTAT STATDT IS PA INSPDT ST LSE FED LSE# NGPA1 NGPA2 NGPADT

DA 81892 DA N 82592 C-30526

DWREC MILTR MIDATE BRADENHEAD INFO: MY CD PR

COMMENTS: WELL NOT YET COMPLETELY PLUGGED AS OF 8/26/92 AS PER LARRY KIDD

W/ PEDC

PF16 TO EXIT

COULDN'T FIND WELL FILE TO DETERMINE INSTATS OF THIS  
SITUATION, BUT BASICALLY IF THE WELL IS NOT PLUGGED WE  
DON'T WANT TO CARRY IT AS AN SYSTEM AS PLUGGED.

OK

BEST IMAGE  
AVAILABLE

Jim,

You may wish to  
review - very unfortunate  
accident.

Don't believe there  
is more for OGCC to do.

DB

8/31/92