

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402946832

Date Received:

02/03/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

TEP

COGCCInspectionReports@terraep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 699804082

Inspection Date: 01/28/2022

FIR Submit Date: 01/31/2022

FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 335103

Location Name: PA-66S95W Number: 32NWSE County: _____

Qtrqr: NWSE Sec: 32 Twp: 6S Range: 95W Meridian: 6

Latitude: 39.479199 Longitude: -108.020050

FACILITY - API Number: 05-045-00 Facility ID: 335103

Facility Name: PA-66S95W Number: 32NWSE

Qtrqr: NWSE Sec: 32 Twp: 6S Range: 95W Meridian: 6

Latitude: 39.479199 Longitude: -108.020050

CORRECTIVE ACTIONS:

1 CA# 159453

Corrective Action: Operators will prevent and minimize adverse impacts to wildlife resources.

Date: 02/07/2022

Response: CA COMPLETED

Date of Completion: 02/02/2022

Operator
Comment:

Vent pipe has been covered with wire mesh and secured. CA completed.

COGCC Decision: _____

COGCC
Representative:

2 CA# 159454

Corrective Action: Oil and gas operators shall implement and maintain Best Management Practices (BMPs) at all oil and gas locations.

Date: 02/15/2022

Response: CA COMPLETED

Date of Completion: 02/03/2022

Operator Comment: Location will be graded and ruts will be removed once the site dries out and conditions allow. TEP continues to restrict access to locations during muddy conditions and educates employees and contractors regarding the importance of minimizing traffic during muddy conditions. See attached response.

COGCC Decision:

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Corrective actions have been addresssed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed:

Title: TEP ENV

Date: 2/3/2022 2:31:18 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402946849	Correspondence
402946851	NO traffic allowed during muddy conditions

Total Attach: 2 Files