



99999999

ADO OIL & GAS CONSERVATION COMMISSION FIELD INSPECTION REPORT



<input checked="" type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION <input type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION		1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100	
API No. 05- 075-63386398		LEASE NAME: Mt. Hope 13	
LOCATION: ^{NESW} C-SW/4 19-9N-53W		OPERATOR: Menahan	
DATE: 5-19-98		INSPECTOR: Ed Burley	
Insp. Type: SR	Insp. Status: PA	PA: Y <input checked="" type="radio"/> N	Pass/Fail: P <input checked="" type="radio"/> F Viol.: Y <input checked="" type="radio"/> N NOV: Y <input type="radio"/> N

INSPECTION ITEM	COMMENTS	INPUT
Well ID Signs (Rule 210, 604.c(4))	Plugged site needs to be cleaned - anchors, tubing, flowline, polish rod, power pole found at site.	
Pits (Reserve/Production) (Rule 902, 903, 904, 905)		
Fences (Rule 603.b.7, 604.C.(3), 1002.A)		
Tank Battery Equipment (Rule 603.b.3, 604)		
Fire Walls/Berms/Dikes (Rule 603.b.12, 604)		
General Housekeeping (Rule 603)		
Spills (Oil/Water) (Rule 907)		
Bradenhead (Rule 207.b)		
Drilling Well/Workover (Rule 317)		
Surface Rehabilitation (Rule 1002, 1003, 1004, 1103)		
Miscellaneous		

JUN 26 1998

CORRECTIVE ACTION REQUIRED: Remove well equipment, restore site to grass.

Date Corrective Action Required By: 6-15-98

Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.



00270029