

FORM  
INSPRev  
X/20

**State of Colorado**  
**Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/13/2022

Submitted Date:

02/13/2022

Document Number:

702100015

**FIELD INSPECTION FORM**

Loc ID 334247 Inspector Name: Beardslee, Tom On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10705  
Name of Operator: EVERGREEN NATURAL RESOURCES LLC  
Address: 1875 LAWRENCE ST STE 1150  
City: DENVER State: CO Zip: 80202

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 3 Number of Comments  
1 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name            | Phone        | Email                      | Comment                         |
|-------------------------|--------------|----------------------------|---------------------------------|
| Distribution, Evergreen | 719-846-7898 | cogcc.evergreen@enrllc.com | <a href="#">All Inspections</a> |

**General Comment:**

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |  |
|------|------|--------|--|--|--|
|      |      |        |  |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type: Bradenhead

# 1

corrective date

Comment:

THIS IS FOLLOW UP TO INSP. DOC #695105574, THE CORRECTIVE ACTION HAS NOT BEEN ADDRESSED. NO YEARLY BRADENHEAD TEST FILED ON ORIGINAL WELL.

Corrective Action:

PERFORM BRADENHEAD TEST AND Submit reports as per RuleS 207/416. (THE ORIGINAL CORRECTIVE ACTION DATE IS STILL VALID.

Date: 02/28/2022

**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**COGCC Comments**

| Comment   | User     | Date       |
|---|----------|------------|
| CA HAS NOT BEEN ADDRESSED BASED ON FIRR DOC #402891961, THE CORRECTIVE ACTION WAS NOT TO PROVIDE ACCESS TO THE BRADENHEAD, THE CORRECTIVE ACTION IS TO PERFORM A BRADENHEAD TEST ON THE ORIGINAL WELL AND SUBMIT IT. (THE FORM 4 THAT IS SUBMITTED COVERSE THE TR WELL ONLY). THE ORIGINIAL WELL HAS TO COMPLY WITH RULE 419 UNLESS OR UNTIL RULE 614 COMPLIANCE IS ACHIEVED. | beardslt | 02/13/2022 |