

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Equipment		corrective date
Type: Bradenhead	# 1	
Comment:	THIS IS FOLLOW UP TO INSP. DOC#695105574, THE CORRECTIVE ACTION HAS NOT BEEN ADDRESSED. NO YEARLY BRADENHEAD TEST FILED ON ORIGINAL WELL.	
Corrective Action:	PERFORM BRADENHEAD TEST AND Submit reports as per RuleS 207/416. (THE ORIGINAL CORRECTIVE ACTION DATE IS STILL VALID.	Date: <u>02/28/2022</u>

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

COGCC Comments

Comment	User	Date
CA HAS NOT BEEN ADDRESSED BASED ON FIRR DOC #402891961, THE CORRECTIVE ACTION WAS NOT TO PRVIDE ACCESS TO THE BRADENHEAD, THE CORRECTIVE ACTION IS TO PERFORM A BRADENHEAD TEST ON THE ORIGINAL WELL AND SUBMIT IT. (THE FORM 4 THAT IS SUBMITTED COVERSE THE TR WELL ONLY). THE ORIGINIAL WELL HAS TO COMPLY WITH RULE 419 UNLESS OR UNTIL RULE 614 COMPLIENCE IS ACHIEVED.	beardslt	02/13/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402955155	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5663429