

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

02/16/2022

Submitted Date:

02/16/2022

Document Number:

699105110**FIELD INSPECTION FORM**Loc ID 452766 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1775 SHERMAN STREET - STE 3000City: DENVER State: CO Zip: 80203**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**14 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
481585	TANK BATTERY	AC	02/10/2022		-	Judy 4N64W6W Tank Battery	AC

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unused equipment needs to be removed for good housekeeping. See attached photo.		
Corrective Action:	Comply with Rule 606	Date:	02/25/2022

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	IGNITOR/COMBUSTOR		
Comment:	Panel		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Gas Meter Run	# 13		
Comment:			
Corrective Action:		Date:	
Type: LACT	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 6		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	#		
Comment:	Solar panel		
Corrective Action:		Date:	

Type: VRU	# 1		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 14		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	#		
Comment:	Missing netting on glycol bulk tank needs to be installed. See attached photo.		
Corrective Action:	Install wildlife protection equipment. Per rule 608.a.(13)		Date: 02/25/2022
Type: Compressor	# 2		
Comment:	Air compressors		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 12		
Comment:			
Corrective Action:			Date:
Type: Vertical Separator	# 4		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 20		
Comment:			
Corrective Action:			Date:
Type: Compressor	# 2		
Comment:			
Corrective Action:			Date:
Type: Other	# 2		
Comment:	EcoVapor Zero		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		40.340800,-104.589100
Comment:	Loadout control tank				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Comment:							
Corrective Action:				Date:			
Contents	#	Capacity	Type	Tank ID	SE GPS		
PRODUCED WATER	2	OTHER	PBV FIBERGLASS		40.340800,-104.589100		
Comment:		Shares containment with crude oil tanks					
Corrective Action:				Date:			
<u>Paint</u>							
Condition							
Other (Content)							
Other (Capacity)		210 BBL					
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Comment:							
Corrective Action:		Date:					
Contents	#	Capacity	Type	Tank ID	SE GPS		
CRUDE OIL	4	OTHER			40.340800,-104.589100		
Comment:							
Corrective Action:		Date:					
<u>Paint</u>							
Condition							
Other (Content)							
Other (Capacity)		538 BBL					
Other (Type)							
<u>Berms</u>							
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Comment:							
Corrective Action:		Date:					
Contents	#	Capacity	Type	Tank ID	SE GPS		
PRODUCED WATER	4	400 BBLs	FIBERGLASS AST		,		
Comment:		has its own containment with other water tanks					
Corrective Action:				Date:			
<u>Paint</u>							
Condition							
Other (Content)							
Other (Capacity)							
Other (Type)							

Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:				Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	5	400 BBLs	STEEL AST		,	
Comment:				has its own containment with other water tanks		
Corrective Action:				Date:		
Paint						
Condition						
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:				Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	20	OTHER			40.340800,-104.589100	
Comment:						
Corrective Action:				Date:		
Paint						
Condition						
Other (Content)						
Other (Capacity)	538 BBL					
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:				Date:		
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
Flaring:						
Type						
Comment:						

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected Facilities

Facility ID: 481585 Type: TANK API Number: - Status: AC Insp. Status: AC

Producing Well

Comment: AC

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday 2/16/22 at approximately 0949hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Judy 4N64W6W Tank Battery of PDC Energy, at Facility ID # 481585 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Unused equipment needs to be removed for good housekeeping. Comply with Rule 606.</p> <p>With a corrective action date of 2/25/22</p> <p>Missing netting on glycol bulk tank needs to be installed. Install wildlife protection equipment. Per rule 608.a.(13). With a corrective action date of 2/25/22</p> <p>See attached photos.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	burnsa	02/16/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402958571	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5666783
699105111	Inspection Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5666779