

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

02/28/2022

Submitted Date:

02/28/2022

Document Number:

701102786

FIELD INSPECTION FORM

Loc ID 314263 Inspector Name: LONGWORTH, MIKE On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 16700
Name of Operator: CHEVRON USA INC
Address: 760 HORIZON DRIVE STE 401
City: GRAND JUNCTION State: CO Zip: 81506

Findings:

- 7 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Regulatory, Rangely		RangelyRegulatr@scoutep.com	All Inspections
Thompson, Bud		BLThomps@BLM.gov	
Sanford, Anita	(970) 675-3842	Anita.Sanford@scoutep.com	All Inspections

General Comment:

[COGCC Routine Inspection Report Summary](#)
Location is in a High Priority Habitat Area.
During this inspection the following compliance issues were observed:
• No evidence of tracking control BMP's.
Location shows signs of lack of stabilization BMP's in some areas (rutting is present).
A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location

Lease Road:			
Type	Access		
comment:	Access road is wet, soft, rutted. Lack of stability. See Storm water report.		
Corrective Action:		Date:	

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	911		
Corrective Action:		Date:	

Good Housekeeping:			
Type	TRASH		
Comment:			
Corrective Action:		Date:	

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Tracking Pad	Fail	Tracking Pad	Fail			No evidence of tracking control BMP's
Berms						
		Compaction	Fail			
Compaction	Fail					

Comment: No evidence of tracking control BMP's
Location shows signs of lack of stabilization BMP's in some areas (rutting is present).

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 03/16/2022

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701102787	Inspection 701102786 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5677170