

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402969726

Date Received:

03/01/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

TEP

Phone

970-285-9377

Email

COGCCInspectionReports@terraep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 700703643

Inspection Date: 12/08/2021

FIR Submit Date: 12/09/2021

FIR Status: _____

Inspected Operator Information:

Company Name: GRIZZLY OPERATING LLC

Company Number: 10531

Address: 5847 SAN FELIPE #3000

City: HOUSTON State: TX Zip: 77057

LOCATION - Location ID: 383325

Location Name: GGU MILLER-66S91W Number: 31SWSE County: _____

Qtrqr: SWSE Sec: 31 Twp: 6S Range: 91W Meridian: 6

Latitude: 39.478781 Longitude: -107.595700

FACILITY - API Number: 05-045- -00 Facility ID: 383325

Facility Name: GGU MILLER-66S91W Number: 31SWSE

Qtrqr: SWSE Sec: 31 Twp: 6S Range: 91W Meridian: 6

Latitude: 39.478781 Longitude: -107.595700

CORRECTIVE ACTIONS:

1 ☒ CA# 158503

Corrective Action: remove all stored equipment

Date: 03/08/2022

Response: CA COMPLETED

Date of Completion: 02/28/2022

Operator

Comment:

The ECD is used as needed to maintain compliance with air emissions at this location. The ECD is NOT unused equipment. See attached response.

COGCC Decision: Approved pending re-inspection

COGCC Representative:			
2	✔	CA# 158504	
Corrective Action:	Install or repair required BMPs		Date: 01/21/2022
Response:	CA COMPLETED		Date of Completion: 02/28/2022
Operator Comment:	Due to onset of winter / mud conditions, work will be conducted in spring of 2022. BMPs will be maintained / repaired when site dries out and conditions allow. See attached response.		
COGCC Decision:	Approved pending re-inspection		
COGCC Representative:			

OPERATOR COMMENT AND SUBMITTAL	
Comment:	All corrective actions have been addressed. See attached responses. TEP requests that inspector please include rule citations supporting all corrective actions.
<p>I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.</p> <p>Print Name: Michael Gardner Signed: _____</p> <p>Title: TEP Env Lead Date: 3/1/2022 3:57:47 PM</p>	

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402969726	FIR RESOLUTION SUBMITTED
402969744	ECD response
402969745	Site stability response
402969748	Rule 1002.f response

Total Attach: 4 Files