

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402877715

Date Received:
11/22/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10690

Name of Operator: IMPETRO RESOURCES LLC

Address: PMB 412 558 CASTLE PINES PKWY

City: CASTLE PINES State: CO Zip: 80108

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Bradley, Sam

Phone

970-593-8626

Email

sbradley.impetro@gmail.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 688311613

Inspection Date: 11/17/2021

FIR Submit Date: 11/20/2021

FIR Status: _____

Inspected Operator Information:

Company Name: IMPETRO RESOURCES LLC

Company Number: 10690

Address: 2820 LOGAN DRIVE

City: LOVELAND State: CO Zip: 80538

LOCATION - Location ID: 316910

Location Name: LOUDDER 14-7-64S53W Number: 7SWSW County: WASHINGTON

Qtrqr: SWS Sec: 7 Twp: 4S Range: 53W Meridian: 6
W

Latitude: 39.711731 Longitude: -103.365777

FACILITY - API Number: 05-121- -00 Facility ID: 233127

Facility Name: LOUDDER 14-7 Number: 2

Qtrqr: SWS Sec: 7 Twp: 4S Range: 53W Meridian: 6
W

Latitude: 39.711731 Longitude: -103.365777

CORRECTIVE ACTIONS:

1 ☒ CA# 158024

Corrective Action: Remove oil from pit per Rule 909.e.

Date: 11/23/2021

Response: CA COMPLETED

Date of Completion: 11/21/2021

Operator Comment: Please see attached picture and call log. There must have been a phone issue... operator did not get a message on 11/17 so was notified when the inspection came through on 11/20. The pumper who was watching this well has been fired. This lease will be shut in until the water tanks can be modified to keep this from happening in the future.

COGCC Decision: Approved

COGCC Representative: Reinspection done on 3/1/2022.

OPERATOR COMMENT AND SUBMITTAL

Comment: Please see attached picture and call log. There must have been a phone issue... operator did not get a message on 11/17 so was notified when the inspection came through on 11/20. The pumper who was watching this well has been fired. This lease will be shut in until the water tanks can be modified to keep this from happening in the future.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sam Bradley

Signed: _____

Title: Managing Member

Date: 11/22/2021 12:27:34 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402877715	FIR RESOLUTION SUBMITTED
402877727	Picture
402877728	Call log 11/17/21

Total Attach: 3 Files