

Inspection Photos
Location Name: ROTH-66N64W /30NWSW
Location #: 323450



Photo #1
Roth 12-30 (05-123-13046) Wellsite
Plugged & Abandoned | PA
Plugging Operations: Cementing | WK
Intermediate plugs cementing



Photo #2
Roth 12-30 Wellsite
Plugged & Abandoned | PA
Plugging Operations: Cementing | WK
Site safety signage

Inspection Photos
Location Name: ROTH-66N64W /30NWSW
Location #: 323450



Photo #3
Roth 12-30 Wellsite
Plugged & Abandoned | PA
Plugging Operations: Cementing | WK
Wellsite entrance signage



Photo #4
Roth 12-30 Wellsite
Plugged & Abandoned | PA
Plugging Operations: Cementing | WK
Battery sign