

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402362826

Date Received:

04/06/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10000

Name of Operator: BP AMERICA PRODUCTION COMPANY

Address: 1199 MAIN AVENUE SUITE 101

City: DURANGO State: CO Zip: 81301

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Beebe, Sabre

970-779-9398

Sabre.Beebe@bpx.com

Inspections, All

SanJuanCOGCC@bp.com

Fischer, Alex

alex.fischer@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 688800506

Inspection Date: 04/18/2019

FIR Submit Date: 05/08/2019

FIR Status: _____

Inspected Operator Information:

Company Name: BP AMERICA PRODUCTION COMPANY

Company Number: 10000

Address: 1199 MAIN AVENUE SUITE 101

City: DURANGO State: CO Zip: 81301

LOCATION - Location ID: 306865

Location Name: LEROY MCCAWE GAS UNIT B- Number: 21NWSE County: LA PLATA
M34N8W

Qtrqtr: NWSE Sec: 21 Twp: 34N Range: 8W Meridian: M

Latitude: 37.173543 Longitude: -107.718506

FACILITY - API Number: 05-067- -00 Facility ID: 270614

Facility Name: LEROY MCCAWE B Number: 2

Qtrqtr: NWSE Sec: 21 Twp: 34N Range: 8W Meridian: M

Latitude: 37.173543 Longitude: -107.718506

CORRECTIVE ACTIONS:

1 ☒ CA# 124994

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a Contact COGCC EPS staff.

Date: 06/07/2019

Response: CA COMPLETED

Date of Completion: 04/02/2020

Verified all work on corrective action completed on location. Bull plug replaced and tightened on load line to prevent future impacts. Impacts removed from location and sent to IEI in NM for bulk remediation in BPX soil

Operator Comment: box. Back fill of all impact removal areas. Location dragged to smooth out ruts.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

2 ☒ CA# 124995

Corrective Action: Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.

Date: 06/07/2019

Response: CA COMPLETED

Date of Completion: 04/02/2020

Operator Comment: Verified all work on corrective action completed on location. Bull plug replaced and tightened on load line to prevent future impacts. Impacts removed from location and sent to IEI in NM for bulk remediation in BPX soil box. Back fill of all impact removal areas. Location dragged to smooth out ruts.

COGCC Decision: Approved pending re-inspection

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Corrective actions verified as complete.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Sabre Beebe

Signed: _____

Title: Specialist

Date: 4/6/2020 12:18:31 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

| <u>Document Number</u> | <u>Description</u> |
|------------------------|------------------------------|
| 402362826 | FIR RESOLUTION FORM |
| 402362845 | completion verification form |
| 402363392 | FIR RESOLUTION SUBMITTED |

Total Attach: 3 Files