

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402981749

Date Received:  
03/10/2022

## FIR RESOLUTION FORM

### Overall Status:

#### CA Summary:

1 of 2 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

#### Additional Operator Contact:

Contact Name

Phone

Email

Murray, Richard

g.richard.murray@state.co.us

Arthur, Denise

denise.arthur@state.co.us

Ramsey, Scott

scott.ramsey@state.co.us

Heil, John

john.heil@state.co.us

Trujillo, Aaron

aaron.trujillo@state.co.us

, Inspections

COGCCInspectionReports@terraep.com

Fischer, Alex

alex.fischer@state.co.us

### COGCC INSPECTION SUMMARY:

FIR Document Number: 702800004

Inspection Date: 02/27/2022

FIR Submit Date: 03/08/2022

FIR Status: \_\_\_\_\_

#### Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

#### LOCATION - Location ID: 335539

Location Name: McPherson

Number: A Pad

County: \_\_\_\_\_

Qtrqtr: NENW

Sec: 16

Twp: 6S

Range: 92W

Meridian: 6

Latitude: 39.531109

Longitude: -107.675932

#### FACILITY - API Number: 05-045-

-00

Facility ID: 335539

Facility Name: McPherson

Number: A Pad

Qtrqtr: NENW

Sec: 16

Twp: 6S

Range: 92W

Meridian: 6

Latitude: 39.531109

Longitude: -107.675932

### CORRECTIVE ACTIONS:

1

CA# 160054

Corrective Action: Comply with Rule 912.a Spills and Releases: Control and contain spill/releases and clean up per Rule 912.a. Immediately stop and clean up.  
24 hours to remove free fluids.  
30-days to remove impacted soil.

912.b. Spill Reporting: Report spill or release of E&P waste or produced fluids.  
Remove free fluids and Contact COGCC EPS staff per Rule 912.b.  
24 hours to remove free fluids.  
24 hours for notification and 72 hours for Initial Form 19 Report.

Date: 03/08/2022

Response: CA COMPLETED

Date of Completion: 03/08/2022

Operator Comment: TEP responded immediately to the location upon being notified of a potential spill by Alex Fischer on 3/07/22 at 12:47 p.m.. TEP responded to, and immediately cleaned up the impacted soils on 3/07/22 - 3/08/22. A confirmation soil sample has been collected and will be sent to an analytical lab for full Table 915-1 analysis to ensure that applicable cleanup standards have been met. This incident is not a reportable event per COGCC Rule 912 as described in the attached response that was sent to COGCC staff on 3/07/22.

COGCC Decision:

COGCC Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: Corrective action #160054 has been completed and addressed. See attached response for a full description of initial response and details.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed:

Title: TEP Env Lead

Date: 3/10/2022 5:29:35 PM

### **ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402981767	Correspondence
-----------	----------------

Total Attach: 1 Files