

TEP
RWF 33-15
Location # 335064



location



location

TEP
RWF 33-15
Location # 335064



location



location



TEP
RWF 33-15
Location # 335064



Lack of cap (Cam lock)



Lack of cap (Cam lock)



TEP
RWF 33-15
Location # 335064



Lack of stabilization/compaction



Lack of stabilization/compaction