



- Photo 1 –



- Photo 2 – Very thin oversparay south of the separator



- Photo 3 – South of the separator



- Photo 4 – West side of the separator



- Photo 5 – West side of the separator



- Photo 56– South side of the separator



- Photo 7 – Overspray (typical)



- Photo 8 – Overspray view northeast



- Photo 9 – Overspray view east



- Photo 10 – Overspray view southeast



- Photo 11 –



- Photo 12 – Overspray and limit of cleanup on top of western pit berm



- Photo 13 – Overspray and limit of cleanup on top of western pit berm



- Photo 14 – Overspray and limit of cleanup on south side of western pit berm



- Photo 15 – Overspray on western pit berm



- Photo 16 – Overspray



- Photo 17 –



- Photo 18 –



- Photo 19 –



- Photo 20 –



- Photo 21 –



- Photo 22 –



- Photo 23 –



- Photo 24 – Wet grass



- Photo 25 – Wet spill path around northwest pit corner



- Photo 26 – Wet spill path around northwest pit corner



- Photo 27 – Wet spill path around northwest pit corner