

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
402904459

Date Received:
12/20/2021

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10758
Name of Operator: OGRIS OPERATING LLC
Address: PO BOX 53467
City: MIDLAND State: TX Zip: 79710

Contact Name and Telephone:
Name: _____
Phone: () _____ Fax: () _____
Email: _____

Additional Operator Contact:

Contact Name	Phone	Email
<u>Fitzgerald, Edie</u>	<u>719-859-1394</u>	<u>efitzgerald@ogrisop.com</u>
<u>Atwater, Bonnie</u>	<u>432-755-0212</u>	<u>batwater@ogrisop.com</u>
<u>Gee, Greg</u>	<u>903-987-0353</u>	<u>gggee@ogrisop.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 693503485
Inspection Date: 09/14/2020 FIR Submit Date: 09/14/2020 FIR Status: _____

Inspected Operator Information:

Company Name: TIMBER CREEK OPERATING LLC Company Number: 10672
Address: 6295 GREENWOOD PLAZA BLVD #100
City: GREENWOOD VILLAGE State: CO Zip: 8111-4978

LOCATION - Location ID: 308031

Location Name: APACHE CANYON-634S68W Number: 13SWSE County: LAS ANIMAS
Qtrqtr: SWSE Sec: 13 Twp: 34S Range: 68W Meridian: 6
Latitude: 37.080550 Longitude: -104.944060

FACILITY - API Number: 05-071-00 Facility ID: 260248

Facility Name: APACHE CANYON Number: 13-15
Qtrqtr: SWSE Sec: 13 Twp: 34S Range: 68W Meridian: 6
Latitude: 37.080550 Longitude: -104.944060

CORRECTIVE ACTIONS:

1 CA# 142097

Corrective Action: Comply with rule 603f Date: _____

Response: CA COMPLETED Date of Completion: 12/16/2021

Operator Comment: ALL UNUSED EQUIPMENT HAS BEEN REMOVED FROM THE LOCATION.

COGCC Decision: Approved

COGCC Representative: Per doc#690202428 all corrective actions appear to have been addressed.

2 CA# 142098

Corrective Action: Install or repair required BMPs per Rule 1002.f Date: _____

Response: CA COMPLETED Date of Completion: 11/05/2021

Operator Comment: THE ROAD SURFACE WAS REGRADED AND CROWNED. THIS CONFIGURATION WILL CREATE SHEET FLOW AND ELIMINATE THE TIRE RUTS/SURFACE EROSION. THE ROAD SURFACE WAS COMPACTED BY UTILIZING A VIBRATION SOIL COMPACTION ROLLER TO PROVIDE STABILIZATION.

COGCC Decision: Approved

COGCC Representative: Per doc#690202428 all corrective actions appear to have been addressed.

3 CA# 142099

Corrective Action: Comply with Rule 603.f . For unused , unmarked flow line risers 24 hrs. to lock out tag out. 30 days to remove riser. Date: _____

Response: CA COMPLETED Date of Completion: 12/16/2021

Operator Comment: ALL UNUSED EQUIPMENT HAS BEEN REMOVED FROM THE LOCATION.

COGCC Decision: Approved

COGCC Representative: Per doc#690202428 all corrective actions appear to have been addressed.

OPERATOR COMMENT AND SUBMITTAL

Comment: ALL CORRECTIVE ACTIONS HAVE BEEN ADDRESSED. SEE ATTACHED PHOTO LOG FOR DETAILS.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Edie Fitzgerald Signed: _____

Title: Sr. Environmental Tech. Date: 12/20/2021 10:55:34 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402904459	FIR RESOLUTION SUBMITTED
402904494	PHOTO LOG

Total Attach: 2 Files