

FORM
INSPRev
X/20

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/17/2022

Submitted Date:

03/17/2022

Document Number:

693506798

FIELD INSPECTION FORM

Loc ID 333643 Inspector Name: Silver, Randy On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10663
Name of Operator: ENDURING RESOURCES LLC
Address: 6300 S SYRACUSE WAY, SUITE 525
City: CENTENNIAL State: CO Zip: 80111

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 4 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Walter, Kyle		kwalter@enduringresources.com	All Inspections
Huntington, Heather		hhuntington@enduringresources.com	All Inspections per email 8/13/2021

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216182	WELL	PR	01/30/2008	GW	067-07788	CLARK 7-1	PR

General Comment:

Inspected Facilities

Facility ID: 216182 Type: WELL API Number: 067-07788 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 03/29/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
Follow up inspection to Doc# 693506036 in response to FIRR #402901829. Based on photos submitted by operator corrective actions appear to have been completed. (Photos attached to FIRR)	silverr	03/17/2022