

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/17/2022

Submitted Date:

03/17/2022

Document Number:

693506799**FIELD INSPECTION FORM**Loc ID 326264 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: **Operator Information:**OGCC Operator Number: 10663Name of Operator: ENDURING RESOURCES LLCAddress: 6300 S SYRACUSE WAY, SUITE 525City: CENTENNIAL State: CO Zip: 80111**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Walter, Kyle		kwalter@enduringresources.com	All Inspections
Huntington, Heather		hhuntington@enduringresources.com	All Inspections per email 8/13/2021

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
216136	WELL	PR	03/08/2002	GW	067-07742	CHANEY 1-1	PR

General Comment:

Inspected FacilitiesFacility ID: 216136 Type: WELL API Number: 067-07742 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 03/30/2021Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

COGCC Comments

Comment

User

Date

Follow up inspection to Doc# 693506042 in response to FIRR #402932624. Based on photos submitted by operator corrective actions appear to have been completed. (Photos attached to FIRR)

silverr

03/17/2022