

TEP
RMV 208-20
Location # 324044



location



location

TEP
RMV 208-20
Location # 324044



location



location

TEP
RMV 208-20
Location # 324044



Mar 17, 2022 at 1:43:40 PM
39 508434, -107.916526 ±4.73m
OGCC

**Lack of stabilization/ compaction/ erosion/
sediment migration**



Mar 17, 2022 at 1:43:52 PM
39 508434, -107.916526 ±4.73m
OGCC

**Lack of stabilization/ compaction/ erosion/
sediment migration**



TEP
RMV 208-20
Location # 324044



lack of stabilization/ compaction/ degrading.



lack of stabilization/ compaction/ degrading.