

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402984329

Date Received:

03/15/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 3 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Arthur, Denise

denise.arthur@state.co.us

.Inspections

COGCCInspectionReports@terraep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 702800019

Inspection Date: 03/07/2022

FIR Submit Date: 03/11/2022

FIR Status: _____

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 336022

Location Name: HANGS-66S92W Number: 9SWSW County: _____

Qtrqr: SWS Sec: 9 Twp: 6S Range: 92W Meridian: 6
W

Latitude: 39.534551 Longitude: -107.678161

FACILITY - API Number: 05-045- -00 Facility ID: 336022

Facility Name: HANGS-66S92W Number: 9SWSW

Qtrqr: SWS Sec: 9 Twp: 6S Range: 92W Meridian: 6
W

Latitude: 39.534551 Longitude: -107.678161

CORRECTIVE ACTIONS:

1 ☒ CA# 160131

Corrective Action: Comply with rule 606.

Date: 03/18/2022

Response: CA COMPLETED

Date of Completion: 03/14/2022

Operator Comment: Weed debris removed.

COGCC Decision: Approved pending re-inspection

COGCC
Representative:

2  CA# 160132

Corrective Action: Comply with Rule 606.

Date: 03/18/2022

Response: CA COMPLETED

Date of Completion: 03/14/2022

Operator
Comment:

Fencing supplies belong to the landowner. TEP is in compliance with Rule 606.a. See attached response.

COGCC Decision: **Not Approved**

COGCC
Representative:

No variance has been requested pursuant to the 502 Rules, per 606.a. It is the responsibility of the Operator to control their Location and keep it in compliance at all times.

OPERATOR COMMENT AND SUBMITTAL

Comment:

Corrective actions # 160131 and #160132 have been completed addressed. See attached response.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed: _____

Title: TEP Env Lead

Date: 3/15/2022 8:01:44 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

402984329	FIR RESOLUTION SUBMITTED
402984341	Correspondence

Total Attach: 2 Files