

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
402981352

Date Received:  
03/10/2022

## FIR RESOLUTION FORM

Overall Status: CAC

### CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

### OPERATOR INFORMATION

OGCC Operator Number: 16700

Name of Operator: CHEVRON USA INC

Address: 760 HORIZON DRIVE STE 401

City: GRAND JUNCTION State: CO Zip: 81506

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Sanford, Anita

970-551-8313

Anita.Sanford@scoutep.com

Regulatory, Rangely

RangelyRegulatr@scoutep.com

Tee Brown

tbrown@scoutep.com

Thompson, Bud

BLThomps@BLM.gov

### COGCC INSPECTION SUMMARY:

FIR Document Number: 701102786

Inspection Date: 02/28/2022

FIR Submit Date: 02/28/2022

FIR Status: \_\_\_\_\_

### Inspected Operator Information:

Company Name: CHEVRON USA INC

Company Number: 16700

Address: 760 HORIZON DRIVE STE 401

City: GRAND JUNCTION State: CO Zip: 81506

### LOCATION - Location ID: 314263

Location Name: A. C. MCLAUGHLIN-62N103W Number: 14NWNE County: \_\_\_\_\_

Qtrqtr: NWNE Sec: 14 Twp: 2N Range: 103W Meridian: 6

Latitude: 40.148490 Longitude: -108.921280

### FACILITY - API Number: 05-103-00 Facility ID: 314263

Facility Name: A. C. MCLAUGHLIN-62N103W Number: 14NWNE

Qtrqtr: NWNE Sec: 14 Twp: 2N Range: 103W Meridian: 6

Latitude: 40.148490 Longitude: -108.921280

### CORRECTIVE ACTIONS:

1 ☒ CA# 159908

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 03/16/2022

Response: CA COMPLETED

Date of Completion: 03/10/2022

DUE TO CURRENT CONDITIONS IN THE RANGELY AREA REQUIRED REPAIRS AND IMPROVEMENTS CAN

Operator  
Comment:

NOT BE MADE UNTIL CONDITIONS IMPROVE. SNOW MELT AND SOFT SURFACES MAKE IT NEXT TO IMPOSSIBLE TO MOVE ANY EQUIPMENT TO MAKE IMPROVEMENTS, MOVEMENT OF SUCH EQUIPMENT WILL ONLY EXACBERATE THE EXISTING STORMWATER PROBLEMS.

AS INDICATED ON THE ATTACHED PICTURE IMPROVEMENTS WILL BE ACCOMPLISHED:

1. RE-ESTABLISH ROAD SIDE DITCHES (RSD'S)
2. GRADE ROADS AND FILL, REMOVE ALL RUTS
3. POSSIBLE WATER BAR TO DIVERT WATER FROM ROADWAY
4. DIVERSION DITCH AS NEEDED TO CONROL THE FLOW OF WATER ONTO ROADWAY AND WELL PAD
5. ADDITIONAL BMP'S AS DETERMINED WHEN CONDITIONS ALLOW A COMPLETE REVIEW OF THE STORMWATER NEEDS.

THE PLAN TO PREVENT FUTHER DAMAGES TO THE ROAD IS TO LIMIT ACCESS TO THE AREA UNTIL THE WORK CAN BE COMPLETED.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: ANITA SANFORD

Signed: \_\_\_\_\_

Title: Regulatory Analyst

Date: 3/10/2022 3:24:59 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
402981352	FIR RESOLUTION SUBMITTED
402981490	FIRR REPONSE PLAN

Total Attach: 2 Files