

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/30/2022

Submitted Date:

03/30/2022

Document Number:

693506977

FIELD INSPECTION FORMLoc ID 318134 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,	303-825-4822	cogcc@kpk.com	All Inspections
Watzman, Ross	(303) 825-4822	rwatzman@kpk.com	all inspections.

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240685	WELL	SI	04/01/2021	GW	123-08473	UPRR 43 PAN AM I 3	SI

General Comment:

THIS IS A FACILITY AND SURFACE EQUIPMENT INSPECTION. ANY CORRECTIVE ACTIONS FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE.

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign not legible		
Corrective Action:	Install sign to comply with Rule 605.g.	Date:	04/30/2022

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 0		
Comment:	Mechanical issue: electric motor missing		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.		Date: 04/30/2022
Type: Ancillary equipment	# 1		
Comment:	electric panel		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 240685 Type: WELL API Number: 123-08473 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI

Corrective Action: _____

Date: _____

BradenHead

Date of Last Brhd Test: 07/08/2021

Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0

Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Wednesday March 30, 2022 at approximately 1:48PM, I, Inspector Randy Silver, conducted an on-site inspection. Location: UPRR 43 PAN AM I #3 Operator: KP Kauffman API#: 123-08473 County: Weld While there, I observed a shut in well site During this inspection the following possible compliance issues were observed: Well sign: Rule 605 g Corrective action date of 4-30-22 see photo 1 Mechanical issue: Rule 608 e Corrective action date of 4-30-22 see photo 2 Weather conditions: cloudy A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	silverr	03/30/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693506978	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5709418