

TEP
KP 13-17
Location # 419675



location



location

TEP
KP 13-17
Location # 419675



location



location

TEP
KP 13-17
Location # 419675



Lack of stabilization/compaction



Lack of stabilization/compaction

TEP
KP 13-17
Location # 419675



Lack of stabilization/erosion.



Lack of stabilization/erosion. BMP's are failing

TEP
KP 13-17
Location # 419675



Lack of stabilization/erosion. BMP's are failing



Lack of stabilization/erosion

TEP
KP 13-17
Location # 419675



Missing cap/plug

