

Inspection Photos
Location Name: PRINTZ-66N64W /31NWNE
Location #: 323561



Photo #1
Printz 2-31 (05-123-13199) Wellsite
Plugged & Abandoned | PA
Plugging Operations: Cementing
Courtesy plug, cement to surface



Photo #2
Printz 2-31 Wellsite
Plugged & Abandoned | PA
Plugging Operations: Kill well | WK
Site safety signage
prior photo

Inspection Photos
Location Name: PRINTZ-66N64W /31NWNE
Location #: 323561



Photo #3
Printz 2-31 Wellsite
Plugged & Abandoned | PA
Plugging Operations: Kill well | WK
Wellsite entrance
prior photo



Photo #4
Printz 2-31 Wellsite
Plugged & Abandoned | PA
Plugging Operations: Kill well | WK
Well Location sign
prior photo