

FORM
INSPRev
X/20

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/30/2022

Submitted Date:

03/30/2022

Document Number:

696304076

FIELD INSPECTION FORM

Loc ID 331970 Inspector Name: PETRIE, ERICA On-Site Inspection 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10673Name of Operator: GADECO LLCAddress: 7535 EAST HAMPDEN AVE STE 400City: DENVER State: CO Zip: 80231**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments1 Number of Corrective Actions

-
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Jenkins, Steve		steve.jenkins@state.co.us	
Burn, Diana		diana.burn@state.co.us	
Trent Green		trent@gfccap.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
269283	WELL	TA	12/01/2018	GW	123-21651	Croissant 4	TA

General Comment:

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	_____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment: _____

Multiple Spills and Releases?

Equipment:

		#			corrective date
Type:	Deadman # & Marked	# 2			
Comment:					
Corrective Action:				Date:	
Type:	Bradenhead	# 1			
Comment:	Appears to be plumbed to surface Form 17 -40281490 dated 09.02.2021 - Test Date: 08.14.2021				
Corrective Action:				Date:	
Type:	Other	# 1			
Comment:	TA Wellhead				
Corrective Action:				Date:	

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 269283 Type: WELL API Number: 123-21651 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: TA - Well found in TA Status. TA Since 12.01.2018. Well Overdue for MIT. Last MIT Form 21 2477083 Dates 01.28.2014 on Record.

Form 42 for MIT - 401550312 Dated 02.20.2018 for a Test Date of 03.05.2018. NO FORM 21 found on Record to correlate with this Form 42.

Form 4 for TA Status 402845375 dated 10.18.2021 Approved by Steve Jenkins on 10.29.2021. On this Form it states that the last MIT was on 08.14.2021. AGAIN NO Form 21 on Record to correlate to an MIT being done on Well.

Only a Form 17 (Bradenhead TEST) date 09.02.2021 with a the Test date of 08.14.2021 is on Record.

Form 17 - Bradenhead Test and Form 21 - MIT (Mechanical Integrity Test) are NOT the SAME THING.

Last MIT performed on Well appears to be done on 01.28.2014 per Form 21 2477083

Form 4 402845375 also states Well to be Plugged and Abandoned in the Future. Well plugging requires an approved Form 6 Intent to Abandon to Plug Well.

Corrective Action: Well was found in state of Temporary Abandonment.

Well is overdue for Mechanical Integrity Test (MIT). MIT require 10 day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to plug well. Per Rule 417.c

Perform successful mechanical integrity test. If a successful MIT can not be performed within 30 day CA time the well must be plugged within 3 months per Rule 417 and 210.

Date: 05/02/2022

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Friday 03/25/2022 at approximately 10:46, I, Inspector Erica Petrie, conducted a Field Inspection at Gadeco, LLC; Croissant #4, Location #331975 in Weld County, Colorado.</p> <p>While there, I observed Production Operations</p> <p>During this Inspection the following possible compliance issues were observed:</p> <p>Well was found in state of Temporary Abandonment.</p> <p>Well is overdue for Mechanical Integrity Test (MIT). MIT require 10 day notification via Form 42. Well plugging requires an approved Form 6 Intent to Abandon to plug well. Per Rule 417.c</p> <p>Perform successful mechanical integrity test. If a successful MIT can not be performed within 30 day CA time the well must be plugged within 3 months per Rule 417 and 210.</p> <p>Corrective Action Date: 05.02.2022</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of the Inspection Report</p>	petrie	03/30/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403000234	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5709864
696304077	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5709837