

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403008630

Date Received:
04/07/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

2 of 8 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10515

Name of Operator: GUNNISON ENERGY LLC

Address: 1801 BROADWAY #1150

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Engineering

dnr_cogccengineering@state.co.us

Byers, Jim

jbyers@blm.gov

Donahue, Jessica

jdonahue@ardorenvironmental.com

Johnston, Tyson

Tyson.Johnston@oxbow.com

Lang, Heather

Heather.Lang@oxbow.com

1

geops@oxbow.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 701102952

Inspection Date: 04/06/2022

FIR Submit Date: 04/07/2022

FIR Status: _____

Inspected Operator Information:

Company Name: GUNNISON ENERGY LLC

Company Number: 10515

Address: 1801 BROADWAY #1150

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 334446

Location Name: HOTCHKISS FEDERAL 12-89-612S89W Number: 20SWNW County: GUNNISON

Qtrqtr: SWN Sec: 20 Twp: 12S Range: 89W Meridian: 6

Latitude: 39.001570 Longitude: -107.367060

FACILITY - API Number: 05-051-00 Facility ID: 294808

Facility Name: DEADMAN GULCH U HOTCHKISS FED Number: 20-12D

Qtrqtr: SWN Sec: 20 Twp: 12S Range: 89W Meridian: 6

Latitude: 39.001570 Longitude: -107.367060

CORRECTIVE ACTIONS:

7 CA# 160786

Corrective Action: Inspect and repair gas leak.

Date: 04/07/2022

Response: CA COMPLETED

Date of Completion: 04/08/2022

Operator Comment: After removal of water from cellar, flanges being inspected for seal leak and bradenhead will be re-tested on 4/8. GE devising bradenhead monitoring plan per discussion with state engineer.

COGCC Decision:

COGCC Representative:

8 CA# 160787

Corrective Action: Remove fluids from containments and well cellar.
Install or repair required BMPs per Rule 1002.f.(2)C

Date: 04/08/2022

Response: CA COMPLETED

Date of Completion: 04/08/2022

Operator Comment: Fluids removed from containment and well cellar.

COGCC Decision:

COGCC Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: Initial response for well cellar water and leak issue.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Tyson Johnston

Signed:

Title: Vice President

Date: 4/7/2022 11:52:37 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

--	--

Total Attach: 0 Files