

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

04/11/2022

Submitted Date:

04/12/2022

Document Number:

696304109

FIELD INSPECTION FORM
 Loc ID 422116 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 96155

Name of Operator: WHITING OIL & GAS CORPORATION

Address: 1700 LINCOLN STREET SUITE 4700

City: DENVER State: CO Zip: 80290

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

14 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Deranleau, Greg		greg.deranleau@state.co.us	
Smith, Sydney		ssmith@fundareresources.com	Regulatory
Kraich, Adam		adam.kraich@state.co.us	
Burn, Diana		diana.burn@state.co.us	
, CODY		ctruitt@fundareresources.com	PRINCIPAL AGENT
Linhardt, Cliff		clinhardt@fundareresources.com	DESIGNATED AGENT

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
422115	WELL	PR	11/01/2021	OW	123-33161	Twomile Creek 22-13H	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Stained Soil at Gas Engine Exhaust and Wellhead , see photos		
Corrective Action:	For localized stained soils or oily waste - "Properly dispose of oily waste in accordance with 905.e."	Date:	04/29/2022

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	

Equipment:

corrective date

Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

Type: Vertical Separator	# 1	
Comment:		
Corrective Action:		Date:
Type: Vertical Heater Treater	# 1	
Comment:		
Corrective Action:		Date:
Type: Flare	# 1	
Comment:	Candlestick Flare DOES NOT Comply with COA on Form 4 DOC 402527862; see photos The expectation for permanent flares controlling separators will be an enclosed combustion device with a 98% design destruction efficiency for hydrocarbons.	
Corrective Action:	Comply with COA Form 4 DOC 402527862	Date:
Type: Emission Control Device	# 1	
Comment:		
Corrective Action:		Date:
Type: Deadman # & Marked	# 4	
Comment:		
Corrective Action:		Date:
Type: Pump Jack	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	400 BBLS	STEEL AST		40.909980,-103.743310
Comment:					
Corrective Action:	Date:				

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:	Date:			

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	Field Flare	
Comment:	Well Producing at the Time of Inspection. Flaring to Produce Well. NOT Following Conditions of Approval per Form 4 402527862 Dated 11.09.2020 Approved on 01.08.2022 and Form 4 402840165 Dated 10.13.2021 Approved on 01.08.2022	
Corrective Action:	Cease Flaring Operations immediately. Per Form 4 4022840165 Comply with rule 903.d	Date: 04/13/2022

Inspected Facilities									
Facility ID:	422115	Type:	WELL	API Number:	123-33161	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:				Date:					

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Monday 04.11.2022 at approximately 12:02, I, Inspector Erica Petrie, conducted a Field Inspection at Fundare Resources LLC, Two Mile Creek 22-13H, Location #422116 in Weld County, Colorado.</p> <p>While there, I observed Production Operations</p> <p>During this Inspection the following possible compliance issues were observed:</p> <p>Well Producing at the Time of Inspection. Flaring to Produce Well. NOT Following Conditions of Approval per Form 4 402527862 Dated 11.09.2020 Approved on 01.08.2022 and Form 4 402840165 Dated 10.13.2021 Approved on 01.08.2022</p> <p>Candlestick Flare DOES NOT Comply with COA on Form 4 DOC 402527862; see photos The expectation for permanent flares controlling separators will be an enclosed combustion device with a 98% design destruction efficiency for hydrocarbons. Comply with COA Form 4 DOC 402527862</p> <p>Flaring: Cease flaring operations immediately. Per Form 4 402840165 Comply with rule 903.d</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of the Inspection Report</p>	petriee	04/12/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696304110	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5721714