

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/15/2022

Submitted Date:

04/15/2022

Document Number:

696304125**FIELD INSPECTION FORM**Loc ID 422116 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: ☐**Operator Information:**

OGCC Operator Number: 96155

Name of Operator: WHITING OIL &amp; GAS CORPORATION

Address: 1700 LINCOLN STREET SUITE 4700

City: DENVER State: CO Zip: 80290

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

6 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Smith, Sydney		ssmith@fundareresources.com	Regulatory
Burn, Diana		diana.burn@state.co.us	
Deranleau, Greg		greg.deranleau@state.co.us	
Kraich, Adam		adam.kraich@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
422115	WELL	PR	11/01/2021	OW	123-33161	Twomile Creek 22-13H	PR

**General Comment:**

Follow-Up Inspection to FIR #696304109 and in Response to FIRR #40314299

**Location**Overall Good: ☐

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type

OTHER

Comment:

Stained Soil at Gas Engine Exhaust has been mitigated  
STILL REMAINS at Wellhead at the time of this Inspection

Corrective Action:

Date:

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Field Flare

Comment:

The subject well was shut in on 4.12.2022 upon receipt of the FIR (Doc# 696304109). The well will be routed to an enclosed combustion device with a 98% design efficiency per rule 903.e and the COA's in the approved Form 4 (DOC #402527862) and an updated variance request will be submitted per the approved Form 4 (DOC #402840165) prior to bringing the well back online.

Corrective Action:

Date:

**Inspected Facilities**Facility ID: 422115 Type: WELL API Number: 123-33161 Status: PR Insp. Status: PR**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: SI - Well has been shut-in, Tubing Valves appear to be in Closed Position at the time of this Inspection.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Thursday 04.14.2022 at approximately 12:43, I, Inspector Erica Petrie, conducted a Follow-Up Field Inspection at Fundare Resources LLC, Two Mile Creek 22-13H, Location #422116 in Weld County, Colorado.</p> <p>While there, I observed Production Operations</p> <p>During this Inspection the following possible compliance issues were observed:</p> <p>Well has been shut-in, Tubing Valves appear to be in Closed Position at the time of this Inspection.</p> <p>Operator's FIRR Response - "The subject well was shut in on 4.12.2022 upon receipt of the FIR (Doc# 696304109). The well will be routed to an enclosed combustion device with a 98% design efficiency per rule 903.e and the COA's in the approved Form 4 (DOC #402527862) and an updated variance request will be submitted per the approved Form 4 (DOC #402840165) prior to bringing the well back online." Per FIRR 40314299 dated 04.13.2022</p> <p>Stained Soil at Gas Engine Exhaust has been mitigated. STILL REMAINS at Wellhead at the time of this Inspection</p> <p>A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of the Inspection Report</p>	petrie	04/15/2022

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696304126	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5725034">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5725034</a>