

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403018841

Date Received:

04/19/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10112

Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC

Address: 5057 KELLER SPRINGS RD STE 650

City: ADDISON State: TX Zip: 75001

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

dnr\_cogccengineering@state.co.us

regulatory@foundationenergy.com

Leonard, Mike mike.leonard@state.co.us

COGCC INSPECTION SUMMARY:

FIR Document Number: 681700928

Inspection Date: 10/17/2017

FIR Submit Date: 10/26/2017

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: FOUNDATION ENERGY MANAGEMENT LLC

Company Number: 10112

Address: 5057 KELLER SPRINGS RD STE 650

City: ADDISON State: TX Zip: 75001

LOCATION - Location ID: 418908

Location Name: WICKSTROM Number: 6-12 County: WELD

Qtrqr: NWS Sec: 6 Twp: 7N Range: 59W Meridian: 6

Latitude: 40.602630 Longitude: -104.028730

FACILITY - API Number: 05-123-00 Facility ID: 418910

Facility Name: WICKSTROM Number: 6-12

Qtrqr: NWS Sec: 6 Twp: 7N Range: 59W Meridian: 6

Latitude: 40.602630 Longitude: -104.028730

CORRECTIVE ACTIONS:

1 CA# 107580

Corrective Action: Contact the Engineering Integrity section to discuss flowline abandonment requirements per Rule 1103. Along with the rule, the COGCC Operator Guidance, Rules 1101, 1102, and 1103: Flowline Guidance 1101 and 1102 guidance document can provide further details.  
Contact dnr\_cogccengineering@state.co.us with resolution plan.

Date: 11/05/2017

Response: CA COMPLETED

Date of Completion: 10/17/2017

Operator Comment: Please reference FIR Doc #691200319. The 1" uncapped flowline referenced in this inspection is actually a 1" above ground line that runs to the line heater from the well as a service gas supply line for the line heater pilot-burner.

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

**2** CA# 107581

Corrective Action: Comply with Rule 603.f .

Date: 11/05/2017

Response: CA COMPLETED

Date of Completion: 08/01/2018

Operator Comment: FIR Doc #691200319 states that weeds had dissipated and the CA is resolved. Inspection date is entered as date of completion.

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

**3** CA# 107582

Corrective Action: Comply with Rule 603.f .

Date: 01/26/2017

Response: CA COMPLETED

Date of Completion: 10/02/2018

Operator Comment: FIR Doc #691200541 states that the unused equipment SW of the wellhead was removed. Inspection date entered as date of completion.

COGCC Decision: \_\_\_\_\_

COGCC Representative: \_\_\_\_\_

**OPERATOR COMMENT AND SUBMITTAL**

Comment: Please reference follow up inspections (Doc #'s: 691200541 & 691200319) as they note that these corrective action items have all been addressed.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Afton Iiams

Signed: \_\_\_\_\_

Title: HSE/Regulatory Technician

Date: 4/19/2022 12:29:37 PM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

**Document Number**      **Description**

--	--

Total Attach: 0 Files