

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403014661

Date Received:

04/13/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 2 CAs from the FIR responded to on this Form

2 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10694

Name of Operator: PROVIDENCE OPERATING LLC DBA POCO OPERATING

Address: 16400 DALLAS PARKWAY SUITE 400

City: DALLAS State: TX Zip: 75428

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Devin Brown

dbrown@providence-energy.com

Meghan Grimes

7202568774

mgrimes@providence-energy.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 697501291

Inspection Date: 04/08/2020

FIR Submit Date: 04/08/2020

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: PETROSHARE CORPORATION

Company Number: 10454

Address: 9635 MAROON CIRCLE #400

City: ENGLEWOOD State: CO Zip: 80112

LOCATION - Location ID: 333075

Location Name: GUTHRIE-61S67W Number: 2NENW County: \_\_\_\_\_

Qtrqtr: NENW Sec: 2 Twp: 1S Range: 67W Meridian: 6

Latitude: 39.998769 Longitude: -104.859941

FACILITY - API Number: 05-001- -00 Facility ID: 333075

Facility Name: GUTHRIE-61S67W Number: 2NENW

Qtrqtr: NENW Sec: 2 Twp: 1S Range: 67W Meridian: 6

Latitude: 39.998769 Longitude: -104.859941

CORRECTIVE ACTIONS:

1 ☒ CA# 137838

Corrective Action: Comply with Rule 1003 to repair all rutting and reseed no later than 5/6/2020 using a seed mixture requested by the surface owner, or a mixture prescribed by the local county NRCS. Establish vegetation with total perennial, non-invasive uniform plant cover of at least eighty (80) percent of reference area levels. Ensure erosion controls are implemented to stabilize the seeded soil. Operator shall continue to monitor and manage this site until the location meets Rule 1003 standards, including weed management.

Date: 05/06/2020

Response: CA COMPLETED

Date of Completion: 04/28/2020

Operator Comment:	See attached pictures		
COGCC Decision:	Approved		
COGCC Representative:	COGCC Staff conducted a follow up inspection FIR Doc.# 697501386 on 4/22/2020 and observed that the Operator had repaired vehicle rutting disturbance. Staff cleared the corrective action and put the issue In Process until the location meets Rule 1003 vegetative standards.		

**2** ☒ CA# 137839

Corrective Action:	Operator shall maintain vehicle tracking BMPs on the oil and gas location to comply with rule 1002.f.(2)F and repair the culvert. Operator shall ensure material tracked onto Lansing Ct. is cleaned up.	Date: <u>04/09/2020</u>
Response:	CA COMPLETED	Date of Completion: <u>04/28/2020</u>
Operator Comment:	See attached pictures	
COGCC Decision:	Approved	
COGCC Representative:	Operator already submitted a FIRR Doc.# 402386292 on 4/30/2020; COGCC Staff approved via AMI on 5/1/2020.	

**OPERATOR COMMENT AND SUBMITTAL**

Comment:  Corrective actions completed and pictures are attached.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Meghan Grimes      Signed: \_\_\_\_\_

Title: Sr. Manager ESG      Date: 4/13/2022 2:59:19 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
403014661	FIR RESOLUTION SUBMITTED
403014715	Picture of CA
403014716	Picture of CA
403014718	Picture of CA

Total Attach: 4 Files