




Today's Date:	4/7/2022					
Well Name:	R AND G 26-2	Location:	Sec: 26	Twn: 033N	Rng: 007W	UL: J
API Number:	05.067.08671	Footage:	1585' FSL & 1480' FEL			
Operator:	Hilcorp Energy Company	Area/Run/MSO:	05	0510	Steven Walters	
Meter #:	0070101		Pipeline:	RC		
INC Number:	693904377	Agency:	COGCC	Inspector:	Jim Hughes	
Type of INC:	Written	Photos Required:	Yes			
Issue of Concern:	<p>On 4/5/2022 Catherine Roy conducted a reclamation and stormwater inspection. During this inspection the following compliance issues were observed:</p> <p><b>Water observed ponding within secondary containment. Does not appear to be from precipitation. -Control and contain spills/releases and clean up per Rule 906.a. Contact EPS Jim Hughes at (970) 903-4072 by 4/9/2022.</b></p> <p><b>Dense Russian thistle debris observed on well pad berms and around facilities. -Remove and properly dispose of weed debris by 5/7/2022. Manage location to prevent weed debris.</b></p> <p>See attached photos for additional detail.</p>					

 insp\_403007218.pdf  
95 KB

 insp\_403007218 photos.pdf  
730 KB

 Re: R AND G 26-2 - INC - 693904377  
Outlook item

**From:** Mitch Killough <mkillough@hilcorp.com>  
**Sent:** Thursday, April 7, 2022 3:06 PM  
**To:** Hughes - DNR, Jim <jimo.hughes@state.co.us>  
**Cc:** catherine.roy@state.co.us; Tammy Jones <tajones@hilcorp.com>; Steven Walters <swalters@hilcorp.com>; Priscilla Shorty <pshorty@hilcorp.com>; Bobby Spearman <bspearman@hilcorp.com>; Cameron Garrett <cgarrett@hilcorp.com>; Patrick Hudman <phudman@hilcorp.com>  
**Subject:** FW: R AND G 26-2 - INC - 693904377  
**Importance:** High

Hi Jim,

In response to the Issue of Concern noted in the INC below, Hilcorp operations conducted a site visit at the R and G 26-2 earlier today. Based on the site visit, the ponded fluids were determined to be stormwater. Refer to the attached Outlook for our operator’s observation.

If you need any additional information regarding this INC, please let us know.

Thanks.

Mitch Killough  
Hilcorp Energy Company  
713-757-5247 (Office)  
281-851-2338 (Mobile)

**From:** Patrick Hudman <phudman@hilcorp.com>  
**Sent:** Thursday, April 7, 2022 1:15 PM  
**To:** Mitch Killough <mkillough@hilcorp.com>  
**Cc:** Tammy Jones <tajones@hilcorp.com>; Steven Walters <swalters@hilcorp.com>; Cameron Garrett <cgarrett@hilcorp.com>; Priscilla Shorty <pshorty@hilcorp.com>  
**Subject:** Re: R AND G 26-2 - INC - 693904377

All,  
The containment around the tanks has a plastic liner. These tend to hold water from rain and snow..I have checked the tanks for leaks and have found nothing currently leaking. I removed some of the gravel under the manway/fire tube flange on both tanks to double check them and they are not leaking at this time. My conclusion is that this is storm water..

Thanks

Pat Hudman

Sent from my iPhone

On Apr 7, 2022, at 10:07 AM, Mitch Killough <mkillough@hilcorp.com> wrote:

Just spoke with Pat. He is going to swing by today and see if the ponded fluids are from a leak or if the fluids are in fact stormwater. Regardless of what Pat finds, I will relay this info to Jim Hughes by tomorrow so that we can meet our deadline.

Thanks.

Mitch Killough  
Hilcorp Energy Company  
713-757-5247 (Office)  
281-851-2338 (Mobile)

**From:** Patrick Hudman <phudman@hilcorp.com>  
**Sent:** Friday, April 29, 2022 2:48 PM  
**To:** Farmington Regulatory Techs <FarmingtonRegulatoryTechs@hilcorp.com>  
**Cc:** Patrick Hudman <phudman@hilcorp.com>  
**Subject:** FW: R AND G 26-2 - INC - 693904377  
**Importance:** High

Weeds have been removed. See Pics.

Thanks

**PATRICK HUDMAN**  
**AREA 5 PRODUCTION**  
**505-320-1225**

 Hilcorp Energy Company



