

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403016161

Date Received:

04/14/2022

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

TEP

Phone

970-285-9377

Email

COGCCInspectionReports@terraep.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 700704045

Inspection Date: 03/31/2022

FIR Submit Date: 04/05/2022

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: TEP ROCKY MOUNTAIN LLC

Company Number: 96850

Address: 1058 COUNTY ROAD 215

City: PARACHUTE State: CO Zip: 81635

LOCATION - Location ID: 335173

Location Name: JOLLEY-66S91W Number: 20NWNE County: \_\_\_\_\_

Qtrqr: NWNE Sec: 20 Twp: 6S Range: 91W Meridian: 6

Latitude: 39.518390 Longitude: -107.576140

FACILITY - API Number: 05-045- -00 Facility ID: 335173

Facility Name: JOLLEY-66S91W Number: 20NWNE

Qtrqr: NWNE Sec: 20 Twp: 6S Range: 91W Meridian: 6

Latitude: 39.518390 Longitude: -107.576140

CORRECTIVE ACTIONS:

1 ☒ CA# 160674

Corrective Action: Remove stained material and Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition.

Date: 04/22/2022

Response: CA COMPLETED

Date of Completion: 04/12/2022

Operator Comment: Corrective action completed.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

2 ☒ CA# 160675

Corrective Action: Remove stored equipment

Date: 05/13/2022

Response: CA COMPLETED

Date of Completion: 04/12/2022

Operator Comment: ECD is used as needed to maintain compliance for this location. This is not un-used equipment. See attached response.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

3 ☒ CA# 160676

Corrective Action: Install or repair required BMPs

Date: 05/13/2022

Response: CA COMPLETED

Date of Completion: 04/12/2022

Operator Comment: Cut slope is sufficiently stable, and BMPs are sufficient to control storm water runoff and to minimize erosion. BMPs are maintained as needed. See attached response.

COGCC Decision: Approved pending re-inspection

COGCC  
Representative:

#### OPERATOR COMMENT AND SUBMITTAL

Comment: All corrective actions have been completed / addressed. See attached responses.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Michael Gardner

Signed: \_\_\_\_\_

Title: TEP Env Lead

Date: 4/14/2022 2:43:41 PM

### ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

Document Number	Description
403016161	FIR RESOLUTION SUBMITTED
403016177	Correspondence
403016180	Correspondence

Total Attach: 3 Files