

Location

Overall Good:

Signs/Marker:

	Type WELLHEAD		
Comment:	Well sign is starting to get weathered. See attached photo.		
Corrective Action:	Install sign to comply with Rule 605.g. Submit photos with FIRR	Date:	06/27/2022

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Stained soil to the north of the well, needs to be removed. See attached photo.		
Corrective Action:	"Properly dispose of oily waste in accordance with 905.e." Submit photos with FIRR	Date:	05/06/2022

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type WELLHEAD

Comment: Panel

Corrective Action:

Date:

Equipment:

			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:		Date:	

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 435422 Type: WELL API Number: 123-38605 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 08/13/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: _____

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Wednesday 4/27/22 at approximately 0854hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Park O-K-4HC of Civitas, at API # 05-123-38605 in Weld County, Colorado. During this inspection the following possible compliance issues were observed: Stained soil to the north of the well, needs to be removed. "Properly dispose of oily waste in accordance with 905.e." With a corrective action date of 5/6/22 Well sign is starting to get weathered. Install sign to comply with Rule 605.g. With a corrective action date of 6/10/22 See attached photos. Submit pictures on FIRR. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	burnsa	04/27/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403029450	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5736717
699105296	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5736706