

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Well sign is starting to get weathered. See attached photo.		
Corrective Action:	Install sign to comply with Rule 605.g. Submit photo with FIRR		Date: 06/27/2022

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:			Date:

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected FacilitiesFacility ID: 435423 Type: WELL API Number: 123-38606 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 08/13/2021 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

COGCC Comments

Comment

User

Date

COGCC Inspection Report Summary
 On Wednesday 4/27/22 at approximately 0854hrs, I, Inspector Adam Burns,
 Conducted an on-site inspection at Park T-P-4HC of Civitas, at
 API # 05-123-38606 in Weld County, Colorado.
 During this inspection the following possible compliance issues were observed:
 Well sign is starting to get weathered. Install sign to comply with Rule 605.g. With a
 corrective action date of 6/10/22
 See attached photos.
 Submit pictures on FIRR.
 A follow up on this site inspection needs to be conducted to ensure the
 compliance issues have been corrected to comply with COGCC rules.
 This is a summary of inspection report.

burnsa

04/27/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403029453	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5736720
699105298	Inspection Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5736707