

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/27/2022

Submitted Date:

04/28/2022

Document Number:

695106159**FIELD INSPECTION FORM**Loc ID 322268 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 17210Name of Operator: CINNAMON CREEK OIL & GAS INCAddress: P O BOX 544City: WALSH State: CO Zip: 81090**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Mills, Hellen		helening1221@yahoo.com	All Inspections
Mills, Rick	719-324-5630/719-353-2523	rickmills000@gmail.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210091	WELL	PR	09/01/2020	OW	043-40028	JOHNSON & STOCKER 1	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	PHOTO 6: AREA OF IMPACTED SOIL NEAR TANK PHOTO 7: AREA OF IMPACTED SOIL AROUND WELLHEAD. PHOTO 8: AREA OF IMPACTED SOIL OUTSIDE OF BURM NEST TO TANK BATTERY.		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self inspection processes. COMPLY WITH RULE 1002.(2).D.	Date:	05/04/2022

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Bradenhead	# 1		corrective date
Comment:	PHOTO 5: Bradenhead inaccessible or not visible.		
Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2). THIS IS THE SECOND NOTICE IMMEDIATE ACTION IS REQUIRED.	Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	OTHER	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	210 bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate
Comment:				

Inspected FacilitiesFacility ID: 210091 Type: WELL API Number: 043-40028 Status: PR Insp. Status: PR**Producing Well**Comment: Corrective Action: Date: **BradenHead**Date of Last Brhd Test: 03/21/2022Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONEEnd Surf Csg Pressure: 0Comment: Corrective Action: Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
THIS IS A FOLLOW UP TO INSP. DOC #695104229, CA HAS NOT BEEN ADDRESSED FOR ACCESS TO BRADENHEAD. IMMEDIATE ACTION IS REQUIRED. THERE ARE ALSO NEW CA'S FOR IMPACTED SOIL.	beardslt	04/28/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
403030802	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5737823
695106160	INSP. PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5737822