

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/04/2022

Submitted Date:

05/05/2022

Document Number:

699105325

FIELD INSPECTION FORMLoc ID 434756 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 2001 16TH STREET SUITE 900

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

8 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
434757	WELL	PR	02/01/2021	OW	123-38322	CHANDLER STATE D15-72 -1HN	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Adequate		
Corrective Action:			Date: _____

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Unused tote next to the well, needs to be removed for good housekeeping. See attached photo		
Corrective Action:	Comply with Rule 606 Submit photos with FIRR		Date: 05/16/2022

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:			Date:

Equipment:			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:			Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 434757 Type: WELL API Number: 123-38322 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 03/27/2021Annual Brhd Completed? NoLast Brhd Test Results Initial Surf Csg Pressure: 6 Fluid Type: _____End Surf Csg Pressure: 0Comment: Submit reports for BH06/17/2022Corrective Action: Submit reports as per Rule 207.

Date:

COGCC Comments

Comment

User

Date

COGCC Inspection Report Summary
 On Wednesday 5/4/22 at approximately 908hrs, I, Inspector Adam Burns,
 Conducted an on-site inspection at Chandler State D15-72-1HN of Chevron, at
 API # 05-123-38322 in Weld County, Colorado.
 During this inspection the following possible compliance issues were observed:
 Unused tote next to the well, needs to be removed for good housekeeping. Comply with
 Rule 606. With a corrective action date of 5/16/22
 Submit reports for BH. Submit reports as per Rule 207. With a corrective action date of
 6/17/22
 See attached photos.
 Submit pictures on FIRR.
 A follow up on this site inspection needs to be conducted to ensure the
 compliance issues have been corrected to comply with COGCC rules.
 This is a summary of inspection report.

burnsa

05/05/2022

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699105326	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5745720