

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
403041769

Date Received:
05/09/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10679

Name of Operator: LOGOS OPERATING LLC

Address: 2010 AFTON PLACE

City: FARMINGTON State: NM Zip: 87401

Contact Name and Telephone:

Name: _____

Phone: () Fax: ()

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Fischer, Alex

alex.fischer@state.co.us

regulatory@logosresourcesllc.com

Rowley, Darren

drowley@logosresourcesllc.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 688801134

Inspection Date: 04/01/2022

FIR Submit Date: 04/04/2022

FIR Status: _____

Inspected Operator Information:

Company Name: LOGOS OPERATING LLC

Company Number: 10679

Address: 2010 AFTON PLACE

City: FARMINGTON State: NM Zip: 87401

LOCATION - Location ID: 312051

Location Name: BONDAD 33-9-N33N9W Number: 2SESW County: LA PLATA

Qtrqr: SESW Sec: 2 Twp: 33N Range: 9W Meridian: N

Latitude: 37.129100 Longitude: -107.799440

FACILITY - API Number: 05-067-00 Facility ID: 216532

Facility Name: BONDAD 33-9 Number: 22A

Qtrqr: SESW Sec: 2 Twp: 33N Range: 9W Meridian: N

Latitude: 37.129100 Longitude: -107.799440

CORRECTIVE ACTIONS:

1 CA# 160631

Corrective Action: Provide waste manifests with volume and final disposition of material.

Date: 05/04/2022

Response: CA COMPLETED

Date of Completion: 05/02/2022

Operator
Comment:

The excavated material that was stockpiled separately from backfill material and potentially contaminated has been hauled to Envirotechs land farm. Per Rule 905.a.(1): Logos operating handled all material in a way to ensure that E&P Waste was properly stored, handled, transported, treated, recycled, and disposed of, to prevent a threat or actual adverse environmental impact to air, water, soil, or biological resources, or to the extent

necessary to ensure compliance with the concentration levels in Table 915-1, radiation control standards, and WQCC Regulation 41 numeric and narrative Groundwater quality standards and classifications, as incorporated by reference in Rule 901.b.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment: The excavated material that was stockpiled separately from backfill material and potentially contaminated has been hauled to Envirotechs land farm. Per Rule 905.a.(1): Logos operating handled all material in a way to ensure that E&P Waste was properly stored, handled, transported, treated, recycled, and disposed of, to prevent a threat or actual adverse environmental impact to air, water, soil, or biological resources, or to the extent necessary to ensure compliance with the concentration levels in Table 915-1, radiation control standards, and WQCC Regulation 41 numeric and narrative Groundwater quality standards and classifications, as incorporated by reference in Rule 901.b.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Vanesa Fields

Signed: _____

Title: Regulatory Manager

Date: 5/9/2022 11:37:06 AM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

403041961	Waste manifest
-----------	----------------

Total Attach: 1 Files