

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/12/2022

Submitted Date:

05/12/2022

Document Number:

699105364**FIELD INSPECTION FORM**Loc ID 428521 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 8960Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANYAddress: 410 17TH STREET SUITE #1400City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**5 Number of Comments1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Inspections@civiresources.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
435422	WELL	PR	04/01/2021	OW	123-38605	Park O-K-4HC	PR

**General Comment:**

All prior corrective actions still are active. This is a follow up to FIRR #403038232 CA was not corrected did not meet expectations.

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type

OTHER

Comment: Stained soil to the south of the well, needs to be removed. well. See attached photo.

Corrective Action: Comply with Rule 606

Date: 05/10/2022

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 435422 Type: WELL API Number: 123-38605 Status: PR Insp. Status: PR

**Producing Well**Comment: PR

Corrective Action:

Date:

**BradenHead**Date of Last Brhd Test: 08/13/2021 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: \_\_\_\_\_End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

**COGCC Comments**

Comment

User

Date

COGCC Inspection Report Summary  
 On Thursday 5/12/22 at approximately 0720hrs, I, Inspector Adam Burns,  
 Conducted an on-site inspection to FIRR document # 403038232 at Park O-K-4HC of  
 Civitas, at  
 API # 05-123-38605 in Weld County, Colorado.  
 CA did not meet expectations.  
 During this inspection the following possible compliance issues were observed:  
 Stained soil to the south of the well, needs to be removed. Comply with Rule 606. With a  
 corrective action date of 5/6/22  
 Well sign is starting to get weathered. Install sign to comply with Rule 605.g. With a  
 corrective action date of 6/10/22  
 See attached photos.  
 Submit pictures on FIRR.  
 A follow up on this site inspection needs to be conducted to ensure the  
 compliance issues have been corrected to comply with COGCC rules.  
 This is a summary of inspection report.

burnsa

05/12/2022

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
699105365	Inspection Photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5752990">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5752990</a>