

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

403051518

Date Received:

05/17/2022

FIR RESOLUTION FORM

Overall Status:

CA Summary:

3 of 3 CAs from the FIR responded to on this Form

3 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) Fax: ( )

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Romana Cowden

720-951-5895

cogcc.inspections@caerusoilandgas.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 696203608

Inspection Date: 05/02/2022

FIR Submit Date: 05/03/2022

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: CAERUS PICEANCE LLC

Company Number: 10456

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 334752

Location Name: FEDERAL-67S95W Number: 30NWNW County: \_\_\_\_\_

Qtrqr: NWN Sec: 30 Twp: 7S Range: 95W Meridian: 6  
W

Latitude: 39.412490 Longitude: -108.045110

FACILITY - API Number: 05-045- -00 Facility ID: 334752

Facility Name: FEDERAL-67S95W Number: 30NWNW

Qtrqr: NWN Sec: 30 Twp: 7S Range: 95W Meridian: 6  
W

Latitude: 39.412490 Longitude: -108.045110

CORRECTIVE ACTIONS:

1 CA# 161517

Corrective Action: Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition

Date: 05/04/2022

Response: CA COMPLETED

Date of Completion: 05/02/2022

Operator Comment: Route Pumper Tightened Valve stopping leak.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**2** CA# 161518

Corrective Action: Clean and properly dispose in accordance with 905 rules.

Date: 06/03/2022

Response: CA COMPLETED

Date of Completion: 05/03/2022

Operator  
Comment:

Impacted material has been removed from location and properly disposed of.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**3** CA# 161519

Corrective Action: Install or repair required BMPs and maintain per Rule 1002.f.(2)C

Date: 05/10/2022

Response: CA COMPLETED

Date of Completion: 05/02/2022

Operator  
Comment:

Disturbance on location is from Summit Midstream, NOT associated with Caerus.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Romana Cowden

Signed:

Title: EHS

Date: 5/17/2022 10:43:40 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

--	--

Total Attach: 0 Files